


INSTRUCTION MANUAL




■ Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.


■ If you have any question, please feel free to contact us.




MADE IN CHINA




① x2PCS




② x2PCS




③ x1PC




④ x1PC




⑤ x1PC




⑥ x7PCS




⑦ x7PCS




⑧ x6PC



⑨ x6PCS




⑩ x1PC




⑪ x1PC


LIST PART A




M6*12mm
A x 6PCS




M6*25mm
B x 56PCS




M5*45mm
C x 27PCS




D x 13PCS



E x 6PC




F x 2PCS



G x 1PC




H x 2PCS




I x 1PC

1



②		2PCS
④		1PC
⑤		1PC
E		6PCS







2







①		2PCS
A		4PCS
I		1PC

x 2



3





4





5




6







7






8






The arrow must point toward the edge of the board.





9





10









11






12





13






14






15





16



17



18



P12