




L

SCREW 3:
3x30mm=2pcs

Step7



M



R



make sure the iron
mesh towards
the inside



S

SCREW 4:
3x16mm=4pcs
SCREW 5:
4x50mm=4pcs

Step8



N

make sure the iron
mesh towards
the inside

SCREW 1:
4x40mm=4pcs

Step9

