






Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is shown next to a circular icon containing an L-shaped metal bracket and a crossed-out power drill, indicating that a power drill should not be used for this step.
- Warning 2:** A second warning triangle with an exclamation mark is shown next to a circular icon containing a rectangular block being placed on a surface and a crossed-out diagram of the block being placed on a surface with a gap, indicating that the block should be placed directly on the surface.
- Time:** A clock icon is shown next to the text "15'", indicating a 15-minute assembly time.
- Person:** A stick figure icon is shown next to the number "1", indicating that one person is required for assembly.



A	B	C	D	E
		<p>M6 x 15</p>		
x 1	x 2	x 8	x 1	x 4

1



2

