


Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A crossed-out power drill icon indicates that power tools should not be used for this step.
- Warning 2:** A warning triangle icon is positioned above the second warning box.
- Time:** A clock icon indicates a 20-minute assembly time.
- Personnel:** An icon of a person indicates that 2 people are required for assembly.



Additional details within the warning boxes:

- The first warning box contains a crossed-out power drill icon.
- The second warning box contains two diagrams: one showing a rectangular block being placed on a textured surface, and another showing a crossed-out diagram of a block with a hole and a screw, indicating that screws should not be used.




A



B x 3



!



1

