













































ASSEMBLY INSTRUCTION







x4




			
① x 1	② x 1	③ x 1	④ x 1
			
⑤ x 1	⑥ x 1	⑦ x 1	⑧ x 1
			
⑨ x 2	⑩ x 2	⑪ x 1	⑫ x 2
			
⑬ x 2	⑭ x 2	⑮ x 3	⑯ x 4
			
⑰ x 4	⑱ x 4	⑲ x 4	⑳ x 4
			
㉑ x 4	㉒ x 1		

		 Φ 6x30mm	 Φ 4x35mm
A x56+2	B x56+2	C x22+1	D x22+1
 Φ 4x16mm			 Φ 4x12mm
E x6	F x6	G x2	H x2
	 Φ 4x25mm		 Φ 3x14mm
I x2	J x10+1	K x16+1	L x16+1
	 Φ 4x14mm		 Φ 3.5x12mm
M x4	N x24+1	O x8+1	P x32+1
			
CLx4	CRx4	DRx4	DLx4



Step 1






Step 2




Step 3




Step 4






Step 5






Step 6




Step 7






Step 8





Step 9






Step 10





Step 11







Step 12







Step 13






Step 14





Step 15





Step 16





Step 17




Step 18







Step 19



Step 20





Step 21



x4


Step 22




Bx16

x4


Step 23




x4




Bx4



Φ 3.5x12mm
P x16






DRx4



DL x4

Step 25



Step 26

