
















Assembly Instructions




 A1A2 Ax8pcs	 B1B2 Bx20pcs	 ø8X40mm Cx16pcs	 ø6X30mm Dx24pcs
 Ø7*50 6PCS Ex8pcs	 DL CL CR DR L=300mm Fx3pcs	 Gx4pcs	 Hx14pcs
 568mm Ix1pcs	 J₁J₂J₃=3.5*14 J₄=3.5*30J₅ Jx2pcs		 Ø3.5*14 Kx70pcs
 Ø3.5*35 8PCS Lx12pcs	 Mx2pcs	 M6*35 Nx12pcs	 Ox28pcs
 P1P2 M4*12 Px4pcs	 Q1Q2Q3Q4 X2X4X7X3 Qx2pcs	 Rx5pcs	 M6*40 Sx4pcs
 M6*30 Tx1pcs	 U1U2U3U4 X2 Ux1pcs		




X3

STEP 1




	CLx3pcs
	Kx6pcs
	Cx4pcs

STEP 2



	CRx3pcs
	Kx6pcs
	Cx4pcs
	B ₁ x4pcs

STEP 3




Cx4pcs



B₁x4pcs

STEP 4



Q₃x3pcs



Q₄x3pcs



U₄x2pcs




U₂x1pcs




Dx8pcs

STEP 5




B₂x8pcs

STEP 6



X4




Cx4pcs




Dx16pcs

STEP 7





	Q ₁ x2pcs
	Q ₂ x4pcs
	Q ₃ x4pcs
	U ₁ x1pcs
	U ₃ x1pcs

STEP 8




STEP 9




Ex8pcs

STEP 10




Ix1pcs

STEP 11




 A₁x8pcs


STEP 12



 A₂x8pcs





STEP 13




 Sx4pcs

STEP 14




	Kx4pcs
	Nx12pcs
	Rx5pcs
	Tx1pcs

STEP 15




Gx4pcs

STEP 16




STEP 17




P1x4pcs



P2x8pcs





a



b

STEP 18





Mx2pcs




Kx4pcs

STEP 19



Kx24pcs

STEP 20




X3




B₁x12pcs

STEP 21




X3




B₂x12pcs

STEP 22



X3

STEP 23




X3




Lx12pcs


STEP 24



X3



DLx3pcs




DRx3pcs




Kx12pcs

STEP 25




STEP 26



Kx14pcs




Hx14pcs





STEP 27

In order to make the product more beautiful, please paste hardware J on the exposed holes



○ 0x20pcs

STEP 28



	J ₁ x2pcs		
	J ₂ x2pcs		J ₄ x2pcs
	J ₃ x2pcs		J ₅ x2pcs

STEP 29

