











ASSEMBLING INSTRUCTION

<p>A x1PC</p> 	<p>B x1PC</p> 	<p>C x1PC</p> 	<p>D x1PC</p> 
---	---	--	---


<p>E x6PC</p>  <p>M8x30 leg screw fils de vis</p>	<p>F x10PC</p>  <p>M10x20</p>	<p>G x4PC</p>  <p>M10x16 Panel screw Panneau de vis</p>	<p>H x1PC</p>  <p>6#</p>	<p>I x 6 PC</p>  <p>M8</p>	
--	--	--	---	---	--

E x3 I x3 F x3




1

G x4 F x4




2

E x3 I x3 F x3



3



4