



KING





Hardware list:

A M6*15  20PCS	B M6*35  8PCS	C M6*50  8PCS
D M6*20  16PCS	E 4#  2PCS	F B*20  20PCS, installed in slats
1		



Step 1:

C M6*50

8PCS

E 4#

1PC



Step 2:

B M6*35


4PCS

D M6*20

4PCS

E 4#

2PCS




Step 3:

A M6*15

8PCS

E 4#

1PC




Step 4:

A M6*15


4PCS

E 4#

1PC



Step 5:	
A M6*15	8PCS
B M6*35	4PCS
D M6*20	12PCS
E 4#	2PCS



Step 6:

ALL the slats have been installed with caps.

We could make replacement with caps if they were broken.(Hardware Number: F B*20)

