










HARDWARE

A	 15mm M6x70mm	10
B		10
C	 Ø8x30mm	24
D	 8mm Ø4x30mm	44
E		01
F	 8mm Ø4x25mm	24

G		04
H	 7mm Ø3x16mm	08
I		36
J		36
K		22




01




C	 Ø8x30mm	24
---	--	----


02




A	 15mm	 M6x70mm	10
B			10

03




D	 8mm	 Ø4x30mm	24
---	--	--	----

04




F



24

05




I




16

06



J		16
---	---	----



07



K		22
---	---	----

08



4x




I		16
J		16


09

4x




D	 8mm Ø4x30mm	16
---	--	----

10





11




I		04
J		04

12



D	 8mm $\varnothing 4 \times 30 \text{mm}$	04
---	---	----

13



G		04
H	 7mm $\varnothing 3 \times 16 \text{mm}$	08

14

