
## ASSEMBLING INSTRUCTIONS

## THE DRAWERS ARE NEEDED TO BUY ADDITIONAL



| P1 |                 |           | 14 PCS | P9  | 0    |         | 4 PCS  |
|----|-----------------|-----------|--------|-----|------|---------|--------|
| P2 |                 | 0         | 14 PCS | P10 | @mm> | M5x40mm | 16 PCS |
| Р3 | (A) 11111111111 | M4X35mm   | 2 PCS  | P11 | 0    |         | 16 PCS |
| P4 | 9               | M8x30mm   | 18 PCS | P12 |      |         | 1 PC   |
| P5 | (I)111111>      | M3.5x12mm | 2 PCS  | P13 | -    |         | 4 PCS  |
| P7 | 5               |           | 2 PCS  |     |      |         |        |
| D8 | •               |           | 2 PCS  |     |      |         |        |

1

