




















IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY

1		x1
2		x2
3		x1
4		x1
5		x1
6		x3
7		x3
8		x2
9		x1
10		x1
2		




A		X4
B	 M7*50	X40
C		X4
F	 ϕ 6*30	X12
Q	 M3. 5*14	X2
X		X1
Z		X1
 		









3



Ⓐ 4PCS




① 1PC



4



Ⓑ 4PCS





5




5



B 2PCS


4 1PC


5 1PC


Pay attention to the enlarged area of the hole position above





6


C 4PCS








7



B 8PCS


F 8PCS


2 2PCS


6 2PCS


7 2PCS




The side with more
holes facing
downwards




x2




8


B 2PCS






7





13





Attention: For safety and stability, we suggest you have to secure the anti-tip accessories to the wall to prevent tipping, injury, and property damage.

