





Installation Manual






①x6pc




②x3pc




③x6pc




④x12 pc



⑤x1pc



⑥x2pc




6X10

Ⓐx54pc



Ⓑx62pc



6X30

Ⓒx6pc







Ⓓx1pc




6X35

Ⓔx2pc





1


 	 Ⓐ x21pc	 Ⓑ x21pc
--	--	--



X3




2


 	 Ⓐ x18pc	 Ⓑ x18pc
---	--	--



X3





3


 70%	 Ⓐ x15pc	 Ⓑ x15pc
--	--	--







X3


4

 	 C x4pc	 B x2pc
--	---	---








5

 	 © x2pc	 Ⓑ x2pc
---	---	---







6

 70%	 E x2pc	 B x2pc
		



7

 <p>70%</p> 	 <p>ⓑ x2pc</p>
---	---





Tighten all screws to 100% after inspection.

