




Assembly Instruction (WLF-E02)



Parts List Open the hardware check all parts QTY, thanks




A x 1



B x 1



C x 1



D x 1



E x 1



F x 3




G x 4




H x 1

Step 1 ! The screw must be loose to finish




B+C+D+E+F+H





The surface includes
foot pads face up

Step 2 ! The screw must be loose to finish



A+G+H



Tighten all screws to finish