



Diagram illustrating assembly instructions and safety warnings:

- Top Section:** A box containing a wrench icon, a crossed-out power drill icon, and a warning triangle. To the right is a clock icon and the text "15'".
- Bottom Section:** A box containing a block being placed on a surface, a crossed-out block being drilled, and a warning triangle. To the right is a person icon and the text "1".


C




D



D




A




x 1

B




x 4

C



x 1


D



x 2

1

A



x1

B



x2

C





x1

D



x1



2

A



x1

B



x2

D



x1

