
















ASSEMBLY INSTRUCTIONS















CARTON CONTENT:

①x1 	②x1 	③x2 	⑥x12 
⑦x4 	⑧x1 	⑨ x1 	⑩ x1 
⑪ x1 	⑫ x2 	⑬ x2 	Hardware 

PartList:

①x1 	②x1 	③x2 	⑥x12 
⑦x4 	⑧x1 	⑨ x1 	⑩ x1 
⑪ x1 	⑫ x2 	⑬ x2 	

Hardware List:

Ⓐx48  M6x20	Ⓑx4  M6x40	Ⓒx56  M6	Ⓓx4  M6	Ⓔx1  M6
Ⓕx1  M6	Ⓖx2 	Ai — — — — —		


STEP 1

① x1

⑥ x4

Ⓐ x12

Ⓒ x12




STEP 2

③ x1

Ⓑ x2

Ⓒ x4


Ⓓ x2



STEP 3

⑫ x1

⑬ x1




STEP 4

② x1

⑥ x4

A x12

C x12




STEP 5

③ x1

Ⓑ x2

Ⓒ x4


Ⓓ x2



STEP 6

⑫ x1

⑬ x1




STEP 7

⑥ x4

⑧ x1


Ⓐ x12

Ⓒ x12



STEP 8

⑩ x1




STEP 9

⑦ x4

⑨ x1


Ⓐ x12

Ⓒ x12




STEP 10

⑪ x1






STEP 11

Ⓔ x2 








ASSEMBLY INSTRUCTIONS











CARTON CONTENT:

④x2 	⑤x2 	⑥x8 	⑫x2 
⑭x2 	Hardware 		

PartList:

④x2 	⑤x2 	⑥x8 	⑫x2 
⑭x2 			

Hardware List:

Ⓐx24  M6x20	Ⓑx4  M6x40	Ⓒx32  M6	Ⓓx4  M6	Ⓔx1  M6
Ⓕx1  M6	Ⓖx4 			


STEP 1 x2

④ x1

⑥ x4

Ⓐ x12

Ⓒ x12




STEP 2 x2

⑤ x1

Ⓑ x2

Ⓒ x4


Ⓓ x2



STEP 3 x2

⑫ x1

⑭ x1



STEP 4

ⓖ x4 

