


























ASSEMBLY INSRTRUCTION







1








A	B	C	G	I	E	DL	DR
							
x4	x4	M3.5x12 x4	M4x35 x4	x1	M4x18 x1	x1	x1

2






3




A  x5	C  M3.5x12 x15	P  x3	CL  x1	CR  x1
--	---	--	---	---


4



5



6



D



x6

F



M4x12 x20

K



x3

L



x2

G




M4x35 x6

N




x20

7




A	B	D	G
			
x2	x2	x4	M4x35 x4


8




G	H	J
		
M4x35 x4	x4	x4

9




C	M	U	T
			
M3.5x12 X12	X2	X8	M3x16 X8

10





A	B	D	C	M	V
					
x9	x9	x 8	M3.5x12 x20	x3	x1







11





A	E	I	O	C
				
x8	M4x18 x2	x2	x4	M3.5x12 x24



A  x8	B  x8	D  x16	B  x8	D  x16
--	--	---	--	---



A  x 7	B  x 7	D  x 8	G  M4x35 x 7
E  M4x18 x 1	I  x 1	P  x 3	C  M3.5x12 x 9

