




ASSEMBLY INSTRUCTIONS INSTRUCCIONES

4903BK/ 4903WH SIDE TABLE 4903BK/ 4903WH MESA LATERAL


PARTS LIST

NO.	DESCRIPTION	SKETCH	Q'TY
A	TABLE TOP		1
B	LEGS		4
C	SHELF PANEL		1

HARDWARE LIST

NO.	DRAWING	DESCRIPTION	Q'TY
1	Bolt Ø1/4"-20x1-3/4"L		8
2	Screw 8x1-3/8"L		4
3	Handle		1
4	Bolt 4x3/4"L		1
5	Allen key		1
ASSEMBLY TOOL NOT INCLUDED			

STEP/PASO 1:



PAGE 1 OF 2


DO NOT TIGHTEN ALL BOLTS UNTIL COMPLETELY ASSEMBLED.

NO APRETAR LOS TORNILLOS HASTA ARMAR COMPLETAMENTE.


NOTE: PERIODICALLY CHECK TO ENSURE THAT ALL CONNECTORS (BOLTS, SCREWS, ETC.) ARE TIGHT.

NOTA: VERIFIQUE PERIÓDICAMENTE QUE TODOS LOS CONECTORES (TUERCAS, TORNILLOS, ETC.) ESTÉN BIEN APRETADOS

STEP/PASO 2:




STEP/PASO 3:



STEP/PASO 4:

Complete.



DO NOT TIGHTEN ALL BOLTS UNTIL COMPLETELY ASSEMBLED.

NO APRETAR LOS TORNILLOS HASTA ARMAR COMPLETAMENTE.

NOTE: PERIODICALLY CHECK TO ENSURE THAT ALL CONNECTORS (BOLTS, SCREWS, ETC.) ARE TIGHT.

NOTA: VERIFIQUE PERIÓDICAMENTE QUE TODOS LOS CONECTORES (TUERCAS, TORNILLOS, ETC.) ESTÉN BIEN APRETADOS