




















Assembly instruction










Assembly instruction




① x1 	② x4 	③ x1 
④ x1 	⑤ x4 	⑥ x4 
⑦ x4 	⑧ x4 	⑨ x2 
⑩ x2 	⑪ x1 	⑫ x14 
⑬ x1 	⑭ x1 	⑮ x1 
⑯ x1 	⑰ x12 	⑱ x4 
⑲ x4 	⑳ x2 	

Hardware List

A×24 (2+extra)  M8×20mm	B×7(1+extra)  M6×55mm	C×2  M6×40mm
D×39 (3+extra)  M6×32mm	E×24 (1+extra)  M6×15mm	F×49 (4+extra)  M6×10mm
G×5 (1+extra)  M6×15mm	H×2  M4	I×2 
J×2  M8×40mm	K×2  M5×40mm	



1




F×16pcs

M6×10mm


Step 1



Step 2





2




Step 1

F×32pcs


M6×10mm



Step 2



3



A×12pcs




M8×20mm

E×8pcs




M6×15mm



x 2

4





A×4pcs





M8×20mm

I×2pcs



5



B×1pc





M6×55mm

E×4pcs



M6×15mm

6



A×2pcs




M8×20mm


7



A×4pcs




M8×20mm



8



B×2pcs





M6×55mm

E×2pcs




M6×15mm




9



A×2pcs



M8×20mm




10




C×2pcs




M6×40mm




11



B×4pcs




M6×55mm



12



D×6pcs





M6×32mm

E×4pcs



M6×15mm




13




D×12pcs



M6×32mm



14



D×6pcs




M6×32mm

E×4pcs



M6×15mm




15



D×12pcs



M6×32mm




16

F×1pc




M6×10mm


Step 1




Step 2



17



D×3pcs



M6×32mm

E×4pcs




M6×15mm



G×5pcs



M6×15mm



18



J×2pcs




M8×40mm

K×2pcs



M5×40mm

19



Tighten all screws 100%