



CHAIR

(TABACCO)
(PEA)


(GRAPHITE)

PART LIST/Liste des pièces

(1)	(2)	(3)												
 X1	 X1	<table><tr><td>1.</td><td></td><td>X3 $\phi 6$</td></tr><tr><td>2.</td><td></td><td>X1 M6*50</td></tr><tr><td>3.</td><td></td><td>X2 M6*75</td></tr><tr><td>4.</td><td></td><td>X1</td></tr></table>	1.		X3 $\phi 6$	2.		X1 M6*50	3.		X2 M6*75	4.		X1
1.		X3 $\phi 6$												
2.		X1 M6*50												
3.		X2 M6*75												
4.		X1												

INSTRUCTION

A



B

