























2 PERS.


30 MIN


-  
SLOTTED SCREWDRIVER(Not Provided)
-  
POZI SCREWDRIVER(Not Provided)

ASSEMBLY INSTRUCTIONS



A	x 10		Ø6X35mm
B	x 10		Ø15X10mm
C	x 9		M3x12mm
D	x 1		
E	x 3		M4 x 25mm
F	x 3		20mm
G	x 1		
H	x 2		
I	x 10		M4x30 mm
J	x 12		ø6x30mm
K	x 12		
L	x 8		
M	x 10		M3x14 mm
N	x 2		M3x12 mm
N	x 2		
N	x 2		M4x35 mm
N	x 2		

1



M	x 2
M3x14 mm	

A	x 10
Ø6x35 mm	

C	x 5
M3x12 mm	

D	x 1

E	x 3
M4x25 mm	

F	x 3
20 mm	


G	x 1

H	x 2


2


J	x 1
Ø6x30 mm	


I	x 1
M4x30 mm	




3





B	x 4
	
Ø15X10mm	


J	x 4
	
ø6x30mm	


I	x 2
	
M4x30mm	

4





B	x 2
	
Ø15X10mm	


J	x 2
	
ø6x30mm	

I	x 1
	
M4x30mm	


5





I	x 6
	
M4x30mm	

J	x 3
	
ø6x30mm	


6




B	x 4
	
Ø15X10mm	


J	x 2
	
ø6x30mm	


7








8



C	x 4
	
M3x12mm	

K	x 12
	

9



10

