




Ax1




Bx1




Cx1
 $\frac{400 \times 270}{15.7 \times 10.6}$




Dx1



Ex1



Fx2
 $\frac{285 \times 270}{11.2 \times 10.6}$



Gx1
 $\frac{270 \times 268}{10.6 \times 10.5}$



Hx16




Ix16



Jx16



Kx10
M3.5x $\frac{12}{0.5}$



Lx24
M3.5x $\frac{15}{0.6}$



Mx4
M4x $\frac{30}{1.2}$




Nx2



Ox2

Px2



Qx4




Rx4




Sx4



€ \$ £




①




Ix8



Hx8




②



Jx8



③




Ix8



Hx8




④



Jx8




⑤



Qx2	
Lx4	
M3.5x	$\frac{15}{0.6}$

⑤


⑥




Qx2	
Lx4	
M3.5x	$\frac{15}{0.6}$

⑥


7



Lx16
M3.5x $\frac{15}{0.6}$




8







Px2


Kx10
M3.5x $\frac{12}{0.5}$





9



10



Mx2



25
1.0

x2

Ox1

Ox2



Mx4



M3.5x 30
1.2

11


Nx2






Sx4



Rx4



12



13

