



ASSEMBLY INSTRUCTLONS


A  3.5X40=23Pcs

B  3.5X35=12Pcs


C  3.5X25=10Pcs

D  M8X35=2Pcs


E  1Pcs




①×1Pcs




②×1Pcs




③×1Pcs



④×1Pcs




⑤×1Pcs




⑥×1Pcs




⑦×1Pcs




⑧×1Pcs




⑨×1Pcs




⑩×1Pcs




⑪×2Pcs




⑫×1Pcs




⑬×1Pcs




⑭×1Pcs




⑮×1Pcs




⑯×1Pcs



⑰×1Pcs









⑱×2Pcs




⑲×1Pcs

ASSEMBLY INSTRUCTLONS




ASSEMBLY INSTRUCTLONS

7




A  X7Pcs

8



B  X8Pcs

9



C  X4Pcs

10

