


Diagram illustrating assembly instructions and safety warnings:

- Top Section:** Shows a screwdriver and a power drill with a diagonal line through it, indicating that a power drill should not be used. A warning triangle with an exclamation mark is positioned to the right. Below this is a clock icon and the text "90'", indicating a 90-minute assembly time.
- Bottom Section:** Shows a rectangular block being placed on a textured surface and another block being cut with a diagonal line through it, indicating that the block should not be cut. A warning triangle with an exclamation mark is positioned to the right. Below this is a person icon and the number "2", indicating that two people are required for assembly.




1




x 1

2




x 1

3




x 1

4




x 1

5




x 1

6




x 1

7




x 1

8




x 1

9




x 1

10



x 1

11




x 1

12




x 1

13



x 1

14




x 5

A




x 32

B



x 32

C




x 33

D




x 2

E



x 4

F




x 4

G




x 4

H





x 4

I






x 20





1






2






3







4






5







6






7






8



9



10






11

B




x 6




12

11






x 1

C





x 14

x 17



13




D  
M4  
x  
24  
x 2



14


F  
M4  
x  
39  
x 4

G  
x 4





15

H



x 4



16

12




x 1

13




x 1

C





x 8

E




x 4





17

C



x 8





18

I



x 20




19

14



x 5



20

