















Ⓐ x2x1 	Ⓑ x3x1 	Ⓒ x8x1 	Ⓓ x2x1 
Ⓔ x2x1 	Ⓕ x2x1 	Ⓖ x2x1 	Ⓗ x2x1 
① x2x1  M4	② x32x1  M6x $\frac{16 \times 1.0}{0.6 \times 0.04}$	③ x44x1  M6x $\frac{15}{0.6}$	⑤ x20x1  M6x $\frac{40}{1.6}$
⑪ x8x1 	⑨ x8x1 	⑩ x12x1 	⑫ x1x1 



1





2





3





4





3






4





5



A2 x2x4 	B2 x1x4 	C2 x1x4 	D2 x1x4 
1 x2x1  M4	2 x4x4  M6x $\frac{16 \times 1.0}{0.6 \times 0.04}$	3 x4x4  M6x $\frac{15}{0.6}$	4 x4x4  M6x $\frac{30}{1.2}$

1



2

