




Ax4



Bx2




Cx2




Dx2



Ex2



Fx26




Gx6



Hx1



Ix2



M3.5x $\frac{28}{1.1}$



M3

Jx104

Kx1



Lx8



Mx16



Nx2



Ox2



Px2



M6x $\frac{120}{4.7}$


Qx1



Rx32




Sx18



M6x $\frac{60}{2.4}$

Tx8



M7x $\frac{60}{2.4}$

Ux2



M5x $\frac{40}{1.5}$

Vx12



M6

Wx1




M3.5x $\frac{28}{1.1}$

Xx2





M4x $\frac{32}{1.3}$

Yx30




mm
inch

x2





① x2




Sx4



Mx8





② x2




Rx16




③ x2




④ x2




Yx30 
M4x $\frac{32}{1.3}$

⑤ x2



Sx4 
Mx8 


⑥ x2



Rx16




⑦




Sx8




8








9




Qx1		⑥
M6x $\frac{120}{4.7}$		



10



11 x2



Lx4




Wx1

M6




Ux2




M7x⁶⁰_{2.4}

12




Sx2






✗




✓

13





Wx1




M6
Tx4 M6x $\frac{60}{2.4}$

14



Xx2	
M3.5x	$\frac{28}{1.1}$
Wx1	
M6	
Tx4	
M6x	$\frac{60}{2.4}$

15



ZMW091021	S=	$\frac{97}{3.8}$	ZMW002002	S=	$\frac{105}{4.0}$
ZMW091531	S=	$\frac{97}{3.8}$	ZMW002081	S=	$\frac{105}{4.0}$
ZMW091041	S=	$\frac{97}{3.8}$	ZMW002061	S=	$\frac{105}{4.0}$
			ZMW002051	S=	$\frac{105}{4.0}$
			ZMW002041	S=	$\frac{105}{4.0}$
			ZMW002021	S=	$\frac{105}{4.0}$

Jx104	
M3.5x	$\frac{28}{1.1}$

