

Assembly and Installation Steps

Size: Ø500*H2200MM

Step 1

1A.Lock the crossbar to the junction box of the ceiling by using 4pcs of 5/32 screws in the accessories bag.
1B.Connect the wires. The hot/positive(+) wire is the one which has writing on it. The negative(-) wire is the one which has no writing.



Step 2

There are 4 screws and 4 nuts in the plastic bag Hang the lamp to ceiling by attaching the screws to the nuts.

Step 3



Install 6 GU10 (Not included).

Step 4


Tear off the protect film.

Step 5

Buckle the crystal ball and hang the crystal string on the metal ring. The recommended installation sequence is from 1 to 66



① 66 Strand Each 1 pcs
crystal ball 66 pcs




Please note:The parts in this table are completely unassembled,for illustrative purpose.In the actual product that you receive,some parts are assembled and attached together.

WIRE CONNECTION DIAGRAM

Wires met safety standards are recommended to connect the supply circuit.

CAUTION:Risk of fire



CANOPY INSTALLATION INSTRUCTIONS

Please read all instructions carefully.Before you proceed to install, make sure that the power off and remains off until installation is complete.

