







Instruction Manual



Console Table







A 70PCS 	B 70PCS $\Phi 15 \times 11$ 	C 20PCS $\Phi 8 \times 40$ 			
D 24PCS $M5 \times 40$ 	E 8PCS $M5 \times 55$ 	F 8PCS $M6 \times 20$ 	G 14PCS 	H 2PCS 	J 1PCS 

1




2



X2


3



B 12PCS Φ 15*11 	C 8PCS Φ 8*40 
--	--

X2

4




B 12PCS Φ 15*11 	C 8PCS Φ 8*40 
--	--

X2

5


B 4PCS
Φ 15*11



X2


6

B 16PCS
Φ 15*11




X2

7




8




9


B 10PCS $\Phi 15 \times 11$ 	C 4PCS $\Phi 8 \times 40$ 
---	---





10


B 8PCS $\Phi 15 \times 11$ 	J 1PCS 
--	---







13



14

