


























Assembly Instruction







x2

1  570x50x12 x1	2  570x248x15 x1	3  1169x249x15 x1	4  577x158mm x1
5  570x248x15 x1	6  570x59x12 x1	7  1169x249x15 x1	8  570x248x15 x1
9  570x150x12 x1	10  400x250x50 x1	11  449x249x15 x2	12  370x59x15 x2
13  370x248x15 x1	14  370x60x15 x1	15  215x84x12 x1	16  215x84x12 x1
17  521x84x12 x1	18  528x209mm x1	19  563x144x15 x1	20  x2
21  x2	22  558x136x12 x4	23  558x86x12 x2	24  563x375x15 x2


A x 32+3  Φ6X35mm	B x 32+3  Φ15X10mm	C x 28+3  Φ6X30mm	D x 4  Φ4X35mm	E x 10+1  Φ3X12mm
F x 24+2  Φ3.5X14mm	G x 8 	H x 3 H-1  H-2  Φ4X20mm	I x 1 	J x 1 J-1  J-2  Φ4X12mm
K x 4  Φ4X8mm	L x 4 	M x 4 	N x 8  Φ4X12mm	O x 4 
P x 1 P-1  P-2  Φ4X45mm	Q x 10+1  Φ5X40mm	R x 4 R-1  R-2  Φ3X16mm	CL x 1  L200	CR x 1  L200
DL x 1  L200	DR x 1  L200			


1




A	E	L	CL	CR
				
x 22	x 4	x 4	x 1	x 1

2



A	H
	 
x 10	x 1

3




D




x 4

4



B	E	DL	DR
x 4	x 4	x 1	x 1

5




B



x 6

6




x2

F



x 12

7




F



x 8

8



H

H-1





H-2




x 2

9




B	C
	
x 7	x 7

10




B	C
	
x 4	x 2

11




12




C		J	
			
x 9			x 1

13






B	G
	
x 11	x 4

14





R	R-1	R-2
		
		x 4


15




16




17



18




19




C	Q
	
x 5	x 5

20



C	Q
	
x 5	x 5

21



G	M	N
		
x 4	x 4	x 8

22

