




Installation & Assembly




Ax4




Bx4



Cx4




Dx2




Ex2




Fx2




Gx2




Hx2



Ix26




Jx6



Kx2



Lx4



Mx4



Nx66



M8x $\frac{35}{1.5}$
Ox92




M6x $\frac{40}{1.6}$
Px2



Qx66




Rx152



Sx18



Tx1





Ux10




€\$£




x2





② x4





Qx4





a

③ x2




④ x2




④ b



⑤ x2





⑥ x2



⑦ x2




⑧ x2



Ⓒ


⑨ x2




Ox8

M8x $\frac{35}{1.4}$

Nx12




⑩ x2



Qx12



⑪ x2




Rx36



⑪

⑫




Px2




M6x $\frac{40}{1.6}$

⑫

13



Sx6




Tx1



f

14 x2




Ox4




M8x $\frac{35}{1.4}$

Nx4



15 x2




g

Qx4




16




Ox32

M8x $\frac{35}{1.4}$

Nx8




17



Qx8









18





Sx12




19



20



21



22

