



ASSEMBLY INSTRUCTION


type1




type2




type3












type4





(A)	x 18	(B)	x 26	(C)	x 21	(D)	x 8	(E)	x 10	(F)	x 1
											
M6x40		M6x30		M6x12		M7x50		M6x15			

(G)	x 4	(H)	x 1	(I)	x 3
					
		M4			

① x1PC 	② x1PC 	③ x1PC 	
④ x2PCS 	⑤ x2PCS 	⑥ x1PC 	
⑦ x2PCS 	⑧ x1PC 	⑨ x1PC 	
⑩ x1PC 	⑪ x1PC 	⑫ x4PCS 	⑬ x1PC 
⑭ x1PC 	⑮ x4PCS 	⑯ x1PC 	⑰ x2PCS 

1

(E)

x 10

M6x15

2

(A)

x 10


(H)

x 1

M6x40


M4

3




(B)	x 8	(H)	x 1
 M6x30		 M4	

4




(D)	x 8	(H)	x 1
 M7x50		 M4	

5




(A)	x 4	(C)	x 3	(H)	x 1
					
M6x40		M6x12		M4	

6




(A)	x 4	(C)	x 3	(H)	x 1
					
M6x40		M6x12		M4	

7




(B)	x 18	(H)	x 1
			
M6x30		M4	

8




(C)	x 6	(H)	x 1
			
M6x12		M4	

9



(F)	x 1	(G)	x 3	(C)	x 8	(H)	x 1
							
				M6x12		M4	

10



(I)	x 3
	

1

type2

(E) x 10

M6x15

2


(A) x 10

M6x40

(H) x 1


M4

3




(B)	x 8	(H)	x 1
 M6x30		 M4	

4




(D)	x 8	(H)	x 1
 M7x50		 M4	

5




(A)	x 4	(C)	x 3	(H)	x 1
					
M6x40		M6x12		M4	

6




(A)	x 4	(C)	x 3	(H)	x 1
					
M6x40		M6x12		M4	

7




(B)	x 18	(H)	x 1
			
M6x30		M4	

8




(C)	x 6	(H)	x 1
			
M6x12		M4	

9



(F)	x 1	(G)	x 3	(C)	x 8	(H)	x 1
							
				M6x12		M4	



10



(I)	x 3
	

1

type3




(E)	x 10
-----	------



M6x15

2



(A)	x 10	(H)	x 1
-----	------	-----	-----




M6x40





M4

3




(B)	x 8	(H)	x 1
M6x30		M4	

4




(D)	x 8	(H)	x 1
M7x50		M4	

5




(A)	x 4	(H)	x 1
			
M6x40		M4	

6




(A)	x 3	(C)	x 7	(H)	x 1
					
M6x40		M6x12		M4	

7




(B)	x 18	(H)	x 1
			
M6x30		M4	

8




(C)	x 6	(H)	x 1
			
M6x12		M4	

9



(G)	x 4	(C)	x 8	(H)	x 1
					
		M6x12		M4	

10



(I)	x 3
	


1

(E)	x 10
 M6x15	

2



(A)	x 10	(H)	x 1
 M6x40		 M4	

3




(B)	x 8	(H)	x 1
M6x30		M4	

4




(D)	x 8	(H)	x 1
M7x50		M4	

5




(A)	x 4	(C)	x 3	(H)	x 1
					
M6x40		M6x12		M4	

6




(A)	x 3	(C)	x 4	(H)	x 1
					
M6x40		M6x12		M4	

7




(B)	x 18	(H)	x 1
			
M6x30		M4	

8




(C)	x 6	(H)	x 1
			
M6x12		M4	

9



Ⓔ	x 4	Ⓒ	x 8	Ⓕ	x 1
					
		M6x12		M4	

10



Ⓘ	x 3
	