


YCMT2510002B-F/Q
Version:1.0



Brand Concept

With over two decades of craftsmanship and manufacturing expertise, we blend thoughtful design with advanced production technology. Every piece is built to meet the standards of leading global brands, delivering exceptional quality you can trust.

Your satisfaction is at the heart of everything we do. If you experience any issues, please feel free to reach out to us—we are always here to help.

Reminder: Please ensure the product is used according to the instructions for the best experience.

Our Service

- **60-Day Parts Guarantee** — Free replacement for any missing or damaged parts.
- **90-Day Quality Assurance** — We will assist you with any quality-related issues.
- **24-Hour Customer Support** — Our team is available around the clock to provide fast and friendly assistance.


After-Sale Contact:

taifurniture_service@outlook.com

For a clearer and smoother assembly experience, please scan the QR code below to watch the installation video :

[QR CODE HERE]





Hardware List:

Ⓐ x 42	Ⓑ x 10	Ⓒ x 8	Ⓓ x 8	Ⓔ x 2	Ⓕ x 8
					
M6 x 12 mm	M6 x 35 mm	M6 x 50 mm	M6 x 60 mm	M8 x 35 mm	M8 x 50 mm
Ⓖ x 16	Ⓗ x 1	Ⓘ x 1	Ⓙ x 2	Ⓚ x 2	
					
Ø6.5x15mm	M4	M5	M5	M5	


Part List:




① x 2PCS




② x 2PCS



③ x 2PCS




④ x 2PCS




⑤ x 1PC




⑥ x 1PC




⑦ x 1PC




⑧ x 1PC




⑨ x 1PC




⑩ x 4PCS




⑪ x 2PCS



⑫ x 2PCS




⑬ x 20PCS



⑭ x 2PCS





⑮ x 6PCS



⑯ x 4PCS


Step:1

Fx2		M8X50
I x1		M5





Step:2

Cx4		M6x50
Gx4		M6.5X15
Hx1		M4




Step:3




Fx4		M8X50
I x1		M5


Step:4



Dx4		M6x60
Gx4		M6.5X15
Hx1		M4


Step:5

F x 2		M8X50
I x 1		M5




Step:6

C x 4		M6x50
G x 4		M6.5X15
H x 1		M4




Step:7



Dx4		M6x60
Gx4		M6.5X15
Hx1		M4


Step:8



Ex2		M8x35
I x1		M5


Step:9

Bx2		M6x35
Hx1		M4




Step:10


Bx4		M6x35
Hx1		M4




Step:11




Bx4		M6x35
Hx1		M4




Step:12




Ax12		M6x12
Hx1		M4



Step:13




A x 30		M6 x 12
H x 1		M4




Step:14

Drilling



Step:15

Jx2  M5



Step:16

Kx2  M5

