










HARDWARE




BOX-1/4

NO.	PARTS	QTY
(A)		2
(D)		4




BOX-2/4

NO.	PARTS	QTY
(A1)		2
(D1)		4



BOX-3/4



NO.	PARTS	QTY
(B)		4
(B1)		6
(J)		8

BOX-4/4

NO.	PARTS	QTY
(B1)		2
(C)		4
(G)		1
(F)		7
(F1)		7
(E)		8
(H)		8
(I)		4
1 ↓ 13		1




Permanent Installation Examples





1	x 16
M8*50	
9	x32
M4*25	


x4



x4

5 x24
M3*20


04




x4

1 x8
M8*50
9 x16
M4*25


05



x2




② x 4
M10*170
③ x 4
M10*60




x2


② x 4
M10*170







4	x 8
M8*35	
6	x 8
M4*40	



4	x 8
M8*35	
6	x 8
M4*40	








**x7****x7**

⑧ x 24

8



6 x16
M4*40



7 x16
M8*60

