


## 30Mins




 $x^2$ 



**CUSTOMER FIRST, SERVICE FOREMOST!** 

## **Exploded View**

Note: When assembly, do not tighten the screws one by one first until making sure all the corresponding screws are placed in the right positions.



Label	Part Image	Description	Qty
Α		M6x20mm	x12
В	<b>()</b> 1111111111	M6x50mm	x16+1
С	<b>(</b> )11111111	M8x40mm	x12+1
D	<b>(</b> )11111	M6x12mm	x24+1
Е		M4 Allen Key	x1
F		Corner Protector	x12
G		M6 Allen Key	x1
1		Table Board	<b>x</b> 1
2		Bench Board	<b>x2</b>
3		Table Leg	x2
4		Table Frame	x2
<b>(5</b> )		Bench Leg	x4
6		Bench Frame	<b>x4</b>
7		Connecting Bar	x12
8		Table Leg Frame	x2

