

WICKER ROCKING BISTRO SET

ASSEMBLY MANUAL




ROCKING WICKER BISTRO SET




Assembly Instruction

- Before assembling, make sure that you lay out and identify all parts listed below in the parts list.
- Install on level ground.
- Keep in mind that not to tighten screw until you fully set up ,After set up, fully tighten screws.
- Any question, please contact our customer service by Email: info@kozyard.com or call toll free: 886-355-0018.





ROCKING CHAIR (DO THIS TWO TIMES)

		1	
Item No.	Reference Image	Description	QTY
A		Seat Back	1pc
В		Seat Base	1pc
C1		Right Arm Rest	1pc
C2		Left Arm Rest	1pc
D		Seat Back Support	1pc
Е	0	M6x35 Socket Head Cap Sœew	4pcs
F		M6x20 Socket Head Cap Screw	8pcs
G	0	Flat Washer	12pcs
Н	0	Screw Cover	12pcs
I		4-mm Allen Key	1pc



• Attach the seatback (A) and the seat base (B) using a M6 x 35 socket head cap screw (E) with a flat washer (G). Do this in two places.







Flip the assembly upside down . Secure the arm rests(C&D) to the seat base (B) using M6 x 20 screws (F) with a washer (G). Do this in four places.

ROCKING CHAIR (DO THIS TWO TIMES)

Flip the assembly back. Secure the seat back (A) using M6 x 35 screws (E) with a washer (G). Do this in two places.




Attach the seat back support (D) using M6 x 20 screws (F) With a washer (G). Do this in four places.




Completly assembly, then fix and tighten all the screws. Finally place the screw covers (H) over them.

COFFEE TABLE


Item			OT) (
No.	Reference Image	Description	QTY
Ј		Table Top	1pc
K		Legs	2pcs
L		Leg Support	2pcs
M		Glass Top	1pc
Е	0	M6x35 Socket Head Cap Screw	4pcs
F	()	M6x20 Socket Head Cap Screw	8pcs
G	0	Flat Washer	12pcs
Н	0	Saew Cover	12pcs
I		4-mm Allen Key	1pc



Flip the assembly upside down. Attach the table top (J) and the legs(K) using a M6x35 socket head cap screw (E) with a flat washer (G). Do this in four places.




With the assembly still flipped over, attach the leg supports (L) using M6x20 socket head cap screw (F) with a flat waher(G). Do this in eight places.



COFFEE TABLE

3. Flip the assembly back then place the glass top (M) on it.



Completly assembly, then fix and tighten all the screws. Finally place the screw Covers (H) over them.