














| | |
|---|---|
| <p>K 4*20</p>  <p>4PCS</p> | <p>L</p>  <p>4PCS</p> |
| <p>A</p>  <p>22PCS</p> | <p>B</p>  <p>22PCS</p> |


| | | | | | | | |
|--|--|---|--|--|---|--|--|
| <p>C 8*40</p>  <p>16PCS</p> | <p>D 3.5*14</p>  <p>52PCS</p> | <p>E</p>  <p>4PCS</p> | <p>F</p>  <p>2PCS</p> | <p>G 568mm</p>  <p>1PCS</p> | <p>H</p>  <p>10PCS</p> | <p>I 3*12</p>  <p>10PCS</p> | <p>J</p>  <p>4PCS</p> |
|--|--|---|--|--|---|--|--|

1




570*270 1PS

2




570*270 1PS

3




1000*270 1PS

4




1000*270 1PS

5




570*270 1PS

6




567*230 1PS

7




570*80 2PS

8




251*282 2PS

9




563*282 2PS

10




570*50 1PS

11



580*263 1PS


12



580*288 2PS


"A" Hardware installation example

I




This part cannot be separated,
please install in strict
accordance with the assembly
requirements


II










III







IV







1



X2








| | |
|---|------|
|  | A*22 |
|  | C*16 |
|  | D*4 |
|  | F*2 |

put A on board ①②③④
 put C on board ①②⑤⑦

2


Make sure the arrow on the screw align to the hole on the side.



B*13


put B on board ①②⑤⑦⑩

4



H*4

5



D*48



E*4




J*4



K*4

6



H*10



I*10

END

