





Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A triangle with an exclamation mark points to a box containing an L-shaped metal bracket and a power drill with a slash through it, indicating that a power drill should not be used for this step.
- Warning 2:** A triangle with an exclamation mark points to a box containing a rectangular block being placed on a surface and a diagram showing a block being secured with a screw.
- Time:** A clock icon indicates a duration of **30'** (30 minutes).
- Person:** An icon of a person indicates that **1** person is required for this step.




A




x 2

B




x 8

C




x 2

D




x 10

E




x 10

F




x 10

G




x 10

H







x 1

I








x 1








1










2






3







4



5




6





7

G




x 10



8

7



x 1

