





Installation Instruction

Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.




MADE IN CHINA


HARDWARE LIST




① ×1PCS




② ×1PCS




③ ×1PCS




④ ×1PCS




⑤ ×1PCS




⑥ ×1PCS




⑦ ×1PCS




⑧ ×1PCS




⑨ ×1PCS




⑩ ×1PCS




⑪ ×1PCS




⑫ ×1PCS




PARTA LIST



M4
A×1PCS




M5X45mm
B×6+2PCS



54x54x120mm
C×4PCS




Ø6*30mm
D×14+2PCS



Ø6x32mm
E1×22+2PCS



Ø15x9.8mm
E2×22+2PCS



80*40*18*mm
F×1PCS




Ø6*M3*10mm
G×2+1PCS



Ø7*M3.5*12mm
H×12+2PCS




Ø8*M4*12mm
I×16+2PCS




Ø8*M4*35mm
J×4+2PCS



CR 1PCS



CL 1PCS




DR 1PCS




DL 1PCS

12Inch/300mm




1PCS

1




H×6PCS
CR×1PCS
CL×1PCS
③×1PCS
④×1PCS

2




E1×12PCS
D×2PCS


3




4




5



6




7




D×6PCS

8




E1×6PCS
①×1PCS

9



E2×6PCS


10



E1×4PCS


⑧×1PCS

11



E2×4PCS
 ⑨×1PCS
 ⑩×1PCS


12



J×4PCS
 ⑪×1PCS
 ⑫×1PCS


P10/12

13




Hx6PCS
DRx1PCS
DLx1PCS

14



Fx1PCS
Gx2PCS

15



16

