





# Assembly Instructions



Your satisfaction is our top priority. If you encounter any issues with this product, such as missing or damaged parts, we're here to help. Please retain the original packaging and take photos of the packaging and the product, then contact us as soon as possible.


## **Warm Tips**

1. Carefully read these instructions and keep them for future reference.
2. Check the parts list and confirm everything's there before starting assembly.
3. When assembling, put all parts on a soft, smooth surface like a carpet to avoid scratches.
4. Don't fully tighten screws until all parts are confirmed in place to avoid misalignment.




We recommend using hand tools for assembly.


If an electric screwdriver is used, reduce power and torque to avoid damage to the product.



## Install the Anti-Tip Straps

Using the anti-tip straps can reduce the risk of tipping over, but can not eliminate it.







**⚠ Caution**

Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for a free replacement if you encounter any damaged or missing parts.

# Parts List




1 1pc




2 1pc




3 1pc



4 1pc




5 1pc




6 1pc



7 6 pcs



8 1pc




9 1pc



# Hardware List

A	X21+1	B	X12+1	C	X6+1	D	X1	E	X4	F	X2+1
M6X12 mm		M6X50 mm		M6X55 mm		M4X55 mm		M6XØ32 mm		Ø4X35 mm	


G	X2	H	X2	I	X3	J	X2+1	K	X4
Ø8X40 mm		L250 mm		40X20 mm		3.5X14 mm		26X13 mm	



# 1

pre-drill 70% 







# 2


screw down 



3


screw down   





C	X6
	
M6X55 mm	


4




pre-drill 70%   






A	X12
	
M6X12 mm	



5



screw down 

A	X6	I	X3
			
M6X12 mm		40X20 mm	


6






J	X2	K	X2
			
3.5X14 mm		26X13 mm	






7



F	X2	G	X2	K	X2
					
Ø4X35 mm		Ø8X40 mm		26X13 mm	

8



H	X2
	
L250 mm	

**Thank you for your support!**

