


INSTRUCTIONMANUAL




■ Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.


■ If you have any question, please feel free to contact us.




HARDWARELIST




① x2PCS




② x2PCS




③ x1PC




④ x8PCS




⑤ x16PCS




⑥ x4PCS




⑦ x1PC



⑧ x2PCS




⑨ x1PC



⑩ x4PCS


LISTPARTA




M5*16mm
A x 32PCS




M6*20mm
B x 12PCS




M6*25mm
C x 8PCS




M6*30mm
D x 48PCS




M6*35mm
E x 16PCS




F x 4PCS



G x 4PCS




H x 8PCS



I x 1PC


1



8		2PCS
A		16PCS
G		4PCS
H		8PCS
I		

x 2



2



7		1PC
A		16PCS
I		



3

NOTE: Please do not fully tighten the screws.






4

NOTE: Please do not fully tighten the screws.







5



NOTE: When all C screws are used in their respective positions, all screws can be tightened.





6



7





8



x 4



P7

9



x 4

10



x 4

11

