	PACKAGED
(A) 1 - (B) 4 -1	
cad all ir	astructions before starting assembly.
tep #1	Assemble the table upside down on a flat, plain and soft surface.
tep #2	Attach the leg #1 and turn to tighten.
itep #3	Align the holes on the stretcher to the leg and attach the bunfoot to lock the stretcher in place.
Step #4	Turn the table on its upright position.
Step #5	Keep this instruction for future reference.
<u>Step #6</u>	Dispose packing materials properly.
	bunfoot
	stretcher
	leg
	table