






Assembly Instruction




  
Hammer and Screwdriver
are not included !!

NO.	QTY.	LINEDRAWING
(A)	18	
(B)	18	
(C)	10	 Ø8x40
(D)	14	 Ø5x40
(E)	2	
(F)	2	
(G)	52	 Ø3.5x14
(H)	4	
(I)	4	
(J)	18	
(K)	8	
(L)	4	
(M)	1	
(N)	26	 Ø3.5x12
(O)	5	


PARTS LIST




NO.	QTY.
①	1
②	1
③	1
④	1
⑤	1
⑥	1
⑦	1
⑧	1
⑨	1
⑩	1
⑪	2
⑫	1
⑬	2
⑭	2
⑮	2
2 OF 6	




A	B	C	J
2x	2x	2x	2x










A	B	C	J
4x	4x	4x	4x




A	B	C	J
4x	4x	4x	4x



A	B	J
8x	8x	8x




9




L		M	
	4x		1x

10




I		H		F		E		N	
	4x		4x		2x		2x		26x

11



G	
	32x

12



K	
	8x

5 OF 6

