
























INSTRUCTION MANUAL
























	
① × 1	② × 1
	
③ × 1	④ × 1
	
⑤ × 1	⑥ × 1
	
⑦ × 1	⑧ × 1
	
⑨ × 1	⑩ × 1
	
⑪ × 1	⑫ × 1

	
⑬ × 4	⑭ × 2
	
⑮ × 1	⑯ × 1
	
⑰ × 1	⑱ × 2
	
⑲ × 1	⑳ × 2
	
㉑ × 1	㉒ × 1
	
㉓ × 4	


The Accessoriess



Hardware Mist


			
Ø6×35 mm	Ø15×10 mm	Ø8×30 mm	Ø3.5×12 mm
A x 24	B x 24	C x 22	D x 8
			
Ø3.5×14 mm	Ø4×35 mm	M6×10 mm	Ø4×14 mm
E x 64	F x 14	G x 8	H x 4
			
I x 2	J x 1	K x 2	L x 2
			
M x 18	N x 4	O x 4	P x 4
			
Q x 4	R x 2	S x 4	T x 2
			
U x 2			

Step 1




T	x 2


Step 2




A	x 6
Ø6×35 mm	


Step 3






B	x 2
 Ø15×10 mm	


Step 4





T1	x 1
	


0	x 2	P	x 2	D	x 2	A	x 4
				 Ø3.5×12mm		 Ø6×35 mm	


Step 5




C	x 2	B	x 2
		 Ø15×10 mm	





Step 6




C	x 4	B	x 4
		 Ø15×10mm	


Step 7




T1	x 1	O	x 2	P	x 2	D	x 2	A	x 5
							Ø3.5×12mm		Ø6×35 mm



Step 8




A	x 5
	Ø6×35 mm

Step 9




C	x 10	B	x 8
		 Ø15×10 mm	

Step 10




B	x 4
 Ø15×10 mm	

Step 11




Please align the holes during this step.



Step 12




C	x 6	F	x 8
		 Ø4×35 mm	



Step 13





G	x 8	J	x 1
			


Step 14



E	x 18	M	x 18
			


Step 15




N	x 4
	

Step 16


I




II





III





IV




S	x 2	E	x 24
			


Step 17




Q	x 4	H	x 4
		 Ø4x14mm	


Step 18













E	x 4
	

Step 19





E	x 2
	

F	x 2	I	x 2	K	x 2	J	x 1
 Ø4× 35 mm							






Step 20




F	x 4
 Ø4×35mm	

Step 21




A	x 4	B	x 4
			

Step 22






T2	x 2	D	x 4

Step 23






S	x 1	E	x 2

Step 24




Step 25



E	x 4	U	x 2
 Ø3.5×14mm			

Step 26

E	x 10	S	x 1
 Ø3.5×14mm		