
















1 Hardware List


A*20 ϕ 8*30mm 	B*25 M6*35mm 	C*25 ϕ 15*10mm 	D*25 M4*45mm 
E*16 M3*12mm 	F*4 M4*20mm 	G*2 22*130*13mm 	H*21 M6*45mm 
I*22 M6*35mm 	J*9 M6*20mm 	K*16 M6*12mm 	L*4 ϕ 16/ ϕ 6.5-2 
M*2 M4mm 	N*4 L340mm N1 N2 		

2 Parts List


①*1 	②*1 	③*2 	④*1 
⑤*1 	⑥*1 	⑦*2 	⑧*2 
⑨*2 	⑩*2 	⑪*1 	⑫*1 
⑬*1 	⑮*1 	⑯*1 	⑰*1 
⑱*2 	⑲*1 	⑳*1 	㉑*1 
㉒*1 	㉓*2 	㉔*2 	㉕*2 
㉖*1 			




STEP 1 D - x 4



STEP 2 D - x 8






STEP 3




x2

STEP 4 C - x 12 B - x 12





STEP 5

E -  x 8 N2 -  x 4




STEP 6


G -  x 2 F -  x 4



STEP 7 N1 - x 4 E - x 8




STEP 8 A - x 10 D - x 13




STEP 9



I -  x 2 M -  x 1




STEP 10

J -  x 9 M -  x 1







STEP 12 H - x 2 M - x 1





STEP 13 K - x 8 M - x 1 H - x 1







STEP 14 H - x 12 M - x 1



STEP 15 A - x 10 B - x 13 C - x 13 I - x 12 M - x 1





STEP 16




STEP 17

K - × 8 M - × 1



STEP 18

H -  x 4 L -  x 4 M -  x 1



STEP 19

I -  x 8 M -  x 1

