




PART LIST

HARDWARE


① x 4	② x 4	
③ x 6	④ x 12	⑤ x 1
⑥ x 4	⑦ x 12	⑧ x 2
⑨ x 4	⑩ x 2	

TOOLS REQUIRED: Phillips Head Screw Driver.


PLEASE TAKE CARE NOT TO OVER-TIGHTEN THE SCREWS.

Step ①

Use 4 x Screw 4 to secure F1 and F2 to Side Panel A.
Use 4 x Screw 4 to secure F3 and F4 to Side Panel A.




Step ②




Insert 4 x Dowel 9 into Back Panel C.
Insert 4 x Bolt 3 into Back Panel C. **Align correctly.**
Secure Back Panel C to F3 using 2 x Screw 1.
Secure Front Panel B to F4 using 2 x Screw 2.

Step ③




Secure 2 x Hinge 8 to Back Panel C using 6 x Screw 7.

Step ④




Insert Panel E. **Ensure the bigger corner cutouts are at the back.**

Step ⑤




Secure F1 to Back Panel C using 2 x Screw 1.
Secure F2 to Front Panel B using 2 x Screw 2.

Step ⑥



Secure 2 x Hinge 8 to Top Panel D using 6 x Screw 7.


Step ⑦



Secure Hinge 5 to Back Panel C using 2 x Screw 6.
Secure Hinge 5 to Top Panel D using 2 x Screw 6.


.....

Step ⑧




Insert 2 x Bolt 3 into Panel G. **Align correctly.**
Secure Panel G to Top Panel D using 2 x Screw 1.

Step ⑨



Secure 2 x Part H to Panel G using 2 x Screw 4.
Lift Top Panel D and secure Part H to Top Panel D using 2 x Screw 4.

COMPLETE



WARNING:
CHOKING HAZARD – Small parts.