





Assembly Instructions







A	x16	B	x16	C	x26	D	x26	E	x4	F	x4	G	x1	H	x8
															
M6*12mm		Ø3.5*14mm		Ø8*30mm		M7*50mm						M4		M6*35mm	

I	x8
	
Ø15mm	


1




X2



X2


H	x4
	
M6*35mm	

2




C	x4	I	x2
			
Ø8*30mm		Ø15mm	

3




I	x2
	
ø15mm	


4




G	x1	C	x8	D	x8
					
M4		Ø8*30mm		M7*50mm	

5




H	x4
	
M6*35mm	

6




I	x4
	
ø15mm	

7





C	x6
	
Ø8*30mm	

8





G	x1	D	x10
			
M4		M7*50mm	

9




C	x8
Ø8*30mm	

10





G	x1	D	x8
M4		M7*50mm	

11




12




B	x16	E	x4	F	x4
					
M3. 5*14mm					

13




G	x1
	
M4	
A	x16
	
M6*12mm	


14





15





16




17



18



19



20

