

Digital thermometer & hygrometer

Features

1. Temperature, humidity and max min value display in same time.
2. Fahrenheit and Celsius is switchable.
3. Maximum and minimum value can be set automatically reset in each 24 hours.

Specifications

1. Temperature measuring range: -10~50°C(14~122 °F)
2. Humidity measuring range: 10%~99%RH
3. Temperature and humidity resolution: 0.1°C(0.1°F); 1%RH
4. Temperature accuracy: ± 1 °C(± 2 °F) Humidity accuracy: $\pm 5\%$
5. Measurement period: 10 S
6. Power supply: 3 Volt CR2032 button battery
7. Size: 76*63*14.3 mm
8. Net weight: 47.5 g

Manuals

1. °F/°C button
Fahrenheit and Celsius unit switch.
2. **ALL TIME/24 HRs** button
Turn on or turn off 24 hours automatically reset max min value function; Hold down this button for 3 seconds to clear the maximum and minimum record value.

Other

1. Comfort level: (independent of temperature)
DRY: less than 30%
OK (COMFORT): 30%~60%
WET: higher than 60%

Attention

1. Keep the screen clean, avoid to dust, oil build-up etc.
2. Don't drop the product .
3. This product is not waterproof, please keep it away from water.
4. When the display dimmed, please replace the battery in time.
5. LCD screen is a capacitive touch screen, please use finger-pulp instead of nails to touch the keys.

Trouble shooting

When buttons not working , please clear LCD by clean fabric with alcohol . Then reboot the thermometer.