









Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.




A		M8x16	46pcs
B		M8x40	4pcs
C		M8x50	8pcs
D		Ø8	7pcs
E		S5	1pc



Step1			
C		M8x50	6pcs
D		Ø8	6pcs
E		S5	1pc




Step2			
A		M8x16	8pcs
E		S5	1pc




Step3

B		M8x40	2pcs
E		S5	1pc






Step4

A		M8x16	8pcs
E		S5	1pc






Step5



A		M8x16	8pcs
E		S5	1pc








Step6


A		M8x16	6pcs
E		S5	1pc






Step7			
A		M8x16	4pcs
E		S5	1pc





Step8			
B		M8x40	2pcs
C		M8x50	1pcs
E		S5	1pc





Step9

C		M8x50	1pcs
D		Ø8	1pcs
E		S5	1pc



Step10

A		M8x16	12pcs
E		S5	1pc

