












Assembly Instruction




NO.	QTY.	LINEDRAWING
(A)	31	
(B)	31	
(C)	22	
(D)	31	
(E)	6	
(F)	20	
(G)	2	



 Hammer and Screwdriver
 are not included !!








PARTS LIST




NO.	QTY.
①	1
②	1
③	1
④	1
⑤	1
⑥	1
⑦	1
⑧	1
⑨	1
⑩	1
⑪	1





1




A		B	
	3x		3x
C		D	
	2x		3x





2




A		B	
	3x		3x
C		D	
	2x		3x





3




A		B	
	2x		2x
C		D	
	2x		2x





4




A		B	
	2x		2x
C		D	
	2x		2x

5








A		B	
	14x		14x
C		D	
	8x		14x

6





7





A		B	
	7x		7x
C		D	
	6x		7x

8



E	
	6x


9



F

20x

10



G

2x