




Assembly Instructions

Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.






1




1 pc

2




1 pc

3




1 pc

4




1 pc

5




1 pc

6




1 pc

7




1 pc

8




2 pcs

9




1 pcs

10




1 pc

11




2 pcs

12




2 pcs

13




1 pc

14




1 pc

15




1 pc

16




1 pc

17




1 pc

18




1 pc

19




1 pc

20




1 pc

21




1 pc

22




1 pc

23




2 pcs

24




1 pc

25




2 pcs

26




2 pcs

27




2 pcs

28




2 pcs

29




2 pcs

30




1 pc

31




1 pc

32




3 pcs

33




1 pc

34




1 pc

35




1 pc

36




1 pc

37




1 pc

38




1 pc

39







1 pc

40




1 pc

A		Ø7*40	91+4 pcs
B		Ø15*10	91+4 pcs
C		Ø8*30	16+1 pcs
D		Ø6*30	16+1 pcs
E		Ø8*50	6 pcs
F		46*15*15	4 pc
G		45*12*1.5	4 pc
H		132*12mm	6 pcs
I		M4*18	8 pcs
J		M4*16	4 pcs
K		300MM	2 pcs

L		350MM	1 set
M		52*25*5	8 pc
N		20*16*9	8 pcs
O		M3.5*30	12+1 pcs
P		M3*14	40+4 pcs
Q		M3*16	48+4 pcs
R		M3.5*14	24+2 pcs
S		Ø6*247	3 pcs
T		482*12*6mm	1 pc
U		65*30*15	2 sets
V			28+2 pcs
W			1 pc

1

A		Ø7*40	X2
---	---	-------	----




2

B


 $\phi 15 \times 10$

X2




3

A

 $\phi 7 \times 40$

X2




4

B




Ø15*10

X2




5

A




Ø7*40

X8





6

B		X8
	Ø15*10	




7

A		X6
	Ø7*40	
K		X2
	CR	
R		X6
	m3. 5*14	




8

D		X4
	Ø6*30	



9

B		X2
	Ø15*10	




10

D



X4




X2

11


B




X4




12

A	 ø7*40	X2
K	 CL	X2
R	 m3. 5*14	X6



13

B	 ø15*10	X2
---	---	----





14

A



Ø7*40

X4





15

B





Ø15*10



X4



16



17




18

A



X6




19


B



X6




20




21

A	 Ø7*40	X12
F	 46*15*15mm	X1
Q	 m3*16	X2




22

B	 ø15*10	X6
E	 ø8*50	X6




23

A	 ø7*40	X6
---	--	----




24

A



X2




25

B



X2




26

D



Ø6*30

X8



27


B




Ø15*10

X4




Attention arrow pointing upwards.



28



29




30

B



Ø15*10

X4




31

B




Ø15*10

X4




Make sure you have at least two people to put the top onto the base.

32




33

B		X2
	Ø15*10	




34

N		X8
20*16*9mm		




35




36

A	 ø7*40	X6
F	 46*15*15mm	X3
Q	 m3*16	X6



37

C	 ø8*30	X6
---	--	----






38

B



X6




39

0




X8





X2

40



X2

41



X2


42

B




Ø15*10

X8



43

H



132*12mm


X2

J





M4*16

X4




44

Q	 m3*16	X12
K	 DR DL	X2 X2








45




46

R	 m3.5*14	X6
L1		X2



47

C	 Ø8*30	X4
---	--	----




48

0



X4




49

A



X3




50

B



Ø15*10

X3



51

R




m3.5*14

X6


L2



X2




52




53

H		X2
I		X4





54

G	 45*12*1.5mm	X2
P	 m3*14	X4



55

M	 52*25*5mm	X4
P	 m3*14	X8




56

P

 m3*14

X8



57

H


 132*12mm

X2

I


 m4*18

X4





58

G	 45*12*1.5mm	X2
P	 m3*14	X4



59

M	 52*25*5mm	X4
P	 m3*14	X8




60

A



X6




61

A



X12




62

B



X6




63

S



X3





64

B



X6





65

B



X6




66

P

 m3*14

X4




67

P


 m3*14

X4



68

V		X28
Q	 m3*16	X28



69

U		X2
65*30*15mm		

