







Diagram illustrating assembly instructions and safety warnings:

- Top Warning:** A crossed-out power drill icon indicates that power tools should not be used for assembly. To the right is a warning triangle with an exclamation mark.
- Time:** A clock icon indicates an estimated assembly time of **10'** (10 minutes).
- Bottom Warning:** Two icons show a block being placed on a surface. The left icon shows the block on a textured mat, and the right icon shows the block on a smooth surface with a crossed-out arrow, indicating that the mat should be used. To the right is a warning triangle with an exclamation mark.
- Person Icon:** A person icon indicates that **1** person is required for assembly.


A




C



B x 3






D x 3



A	B	C	D
x 1	x 3	x 1	x 3

1



2

